

J:\Jobs\030067-01-1b-KingCountyWatershed\030067-01-1b-5-3-2.mxd JWS 6/30/04

Legend

300m Stations

Canopy Cover

- 0% - 20%
- 21% - 40%
- 41% - 60%
- 61% - 80%
- 81% - 100%

Vegetation Type and Quality

- Mature Native, High
- Mature Native, Medium
- Mature Native, Low
- Immature Native, Medium
- Immature Native, Low
- Landscaped/Mowed, Medium
- Landscaped/Mowed, Low
- Invasive, Medium
- Invasive, Low
- Mixed Invasive & Mature Native, Low

Percent Overhanging Vegetation

- 10% Right Bank
- 10% Left Bank
- 23. / River Mile, Tenths






Figure 5-9

Reach 1 (RM 32.1-26.6) Vegetation Characteristics
 Lower Green River Baseline Habitat Survey Report
 King County Water and Land Resources