



Figure 25
**Artificial Channel Constraints
 and Large Woody Debris**

Green-Duwamish River Estuary - Map 3 of 3

*State of the
 Nearshore Report*



Produced by: GIS & Visual Communications Unit, WLR
 King County Department of Natural Resources
 File Name: 0009 SON Est3.ai LP