

































84	Remove creosote piles from subtidal, revegetate riparian and bank crest area	
85	Remove creosote piles and failed pier	
86	Remove 50 creosote piles	
87	Remove 32 creosote piles	
88	Remove 20 creosote piles	





89	Remove large concrete block/footing	
		
90	Remove creosote piles	
		
91	Glacier site – remove creosote piles, dolphins and pier; re-vegetate marine riparian	
		
92	Remove 26 creosote piles and pier remnants	
		





93	Remove relict piles (start) – pilings are not visible in air photos	
		
94	Remove relict piles (end) – pilings are not visible in air photos	
95	Remove wood groin	
		
96	Remove creosote LWD across intertidal	
		
97	Remove 2 creosote piles	
		






98	Remove 50+ creosote piles in intertidal (start)		
99	Remove creosote pilings, failed bulkhead, derelict house in intertidal		
100	Remove creosote dock/barge		
101	Remove creosote, concrete rubble from intertidal and backshore misc. (end)		
102	Remove 12 creosote piles from lower intertidal - subtidal		




103	Remove 70 creosote piles	
104	Remove 2 creosote piles (not visible in photo)	
105	Remove 20 creosote piles (not visible in air photo)	
106	Remove 25 creosote piles (difficult to observe in air photo)	

107	Remove 2 creosote piles (not visible in air photo)	
108	Remove concrete rubble and creosote piles and restore spit – Raab’s Lagoon	 
109	Remove 2 creosote piles (not visible in air photo)	
110	Remove relict wharf piles	

111	Enhance mini-estuary, remove 14 creosote piles and associated fencing and other debris, eradicate invasive species	
112	Remove several small rock groins and protruding bulkhead with fill	
113	Remove 10 creosote piles	
114	Remove concrete rubble	

115	Remove creosote log secured to beach	
116	Remove dam/weir/ fish barrier	
117	Remove concrete debris and failing bulkhead	
118	Remove 4 concrete structures and 10 creosote piles in intertidal (not visible in air photo)	

119	Remove 25 creosote piles (not visible in air photo) in Judd Creek estuary	
120	Remove derelict barge/cannery	 
121	Remove 9 creosote piles	
122	Remove 6 creosote piles	

123	Remove 3 creosote piles	
124	Remove 3 creosote piles	
125	Remove 16 creosote piles from intertidal (not visible in air photo)	
126	Remove creosote logs from marsh	