
Cedar River Wood Hazards
Aerial Survey and Field Inspection, June 2018
Potential Wood Hazards
High Hazard
Signed Hazard
Low Hazard
Needs Inspection
River Miles
1
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
Maplewood Heights
Elliott
Renton Maple Valley Rd
Lake Kathleen
Lake McDonald
Maple Hills
McGarvey Park Open Space
Maple Valley Heights
Cedar Mountain
Cedar Grove
Lake Desire
Otter Lake
Spring Lake/Lake Desire Park
Shady Lake (Mud Lake)
Peterson Lake Natural Area
Lake Youngs
Shadow Lake
Francis Lake
Webster Lake
Four Lakes
Atkinson
Wilderness Village
Orchard
Noble
Meridian Heights
Wilderness
Lake Wilderness
Cedar Creek Park
Pipe Lake
Lake Lucerne
Covington
Maple Valley
Cherokee Bay Park
Summit
Henrys Ridge Open Space
Ravensdale
Henrys
Black
King County
N
0
0.5
1
2
3
4
Miles